



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Oakmont Drive

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 836 L.F. of drainage system. Cleaned out 836 L.F. of roadside ditch. Jetted (2) driveway pipes and (2) crossline pipes. Hydroseeded for erosion control.

Completion: Feb-13

2013-599 / Oakmont Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
CLPJT / Crossline Pipe - Jetted	20.0	\$472.30	\$221.60	\$67.95	\$0.00	\$324.70	\$1,086.55
HAUL / Hauling	40.0	\$874.00	\$428.00	\$161.12	\$0.00	\$576.80	\$2,039.92
HYDR / Hydroseeding	14.0	\$309.79	\$38.95	\$102.76	\$0.00	\$204.44	\$655.93
ONJV / Onsite Job Visit	4.0	\$126.96	\$12.06	\$15.10	\$0.00	\$99.38	\$253.50
RSDCL / Roadside Ditch - Cleanout	70.0	\$1,561.30	\$244.30	\$88.89	\$0.00	\$1,035.90	\$2,930.39
2013-599 / Oakmont Drive Sub Total	148.5	\$3,354.79	\$944.91	\$435.81	\$0.00	\$2,247.83	\$6,983.34
Grand Total	148.5	\$3,354.79	\$944.91	\$435.81	\$0.00	\$2,247.83	\$6,983.34

Before



During



After






Project: Oakmont Drive

Activity: Routine/ Preventive Maintenance

Project #: 2013-599

Township: Port Royal Island

Completed: February 2013



Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe
- Parcels



1 inch = 167 feet