



# Beaufort County Public Works

## Stormwater Infrastructure

### Project Summary

**Project Summary:** Capehart Circle

**Narrative Description of Project:**

Replaced (1) driveway pipe to correct elevation. Installed rip rap for erosion control.

**Completion:** Jul-11

2011-646 / Capehart Circle	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
BKFILL / Back Fill	3.0	\$70.44	\$72.51	\$8.18	\$0.00	\$0.00	\$151.13
DPRPL / Driveway Pipe - Replaced	11.0	\$252.41	\$83.25	\$252.57	\$0.00	\$0.00	\$588.23
HAUL / Hauling	13.0	\$272.82	\$173.03	\$878.68	\$0.00	\$0.00	\$1,324.53
LM / Loading Materials	1.0	\$21.42	\$29.75	\$6.82	\$0.00	\$0.00	\$57.99
UTLOC / Utility locates	1.0	\$20.48	\$0.00	\$0.00	\$0.00	\$0.00	\$20.48
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$595.68	\$595.68
<b>2011-646 / Capehart Circle</b>	<b>41.5</b>	<b>\$914.36</b>	<b>\$465.10</b>	<b>\$1,180.48</b>	<b>\$0.00</b>	<b>\$595.68</b>	<b>\$3,155.62</b>
<b>Sub Total</b>							
<b>Grand Total</b>	<b>41.5</b>	<b>\$914.36</b>	<b>\$465.10</b>	<b>\$1,180.48</b>	<b>\$0.00</b>	<b>\$595.68</b>	<b>\$3,155.62</b>

Before



During



After






Project: Capehart Circle

Activity: Drainage Maintenance

Project #: 2011-646

Township: Port Royal Island














Completed: July 2011



Replaced (1) driveway pipe to correct elevation. Installed rip rap for erosion control.

### Legend

#### Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 138 feet