



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Mint Farm Pond and Outfall

Narrative Description of Project:

Project improved 2,095 L.F. of drainage system. Bush hogged 2,095 L.F. of outfall ditch. Replaced (1) catch basin lid. Installed (1) access pipe, rip rap and hydroseeded for erosion control.

Completion: Aug-11

2012-515 / Mint Farm Pond and Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$20.48	\$0.00	\$0.00	\$0.00	\$0.00	\$20.48
HAUL / Hauling	39.0	\$815.64	\$519.09	\$1,636.83	\$0.00	\$0.00	\$2,971.56
HYDR / Hydroseeding	75.0	\$1,684.93	\$493.48	\$953.33	\$0.00	\$0.00	\$3,131.74
LM / Loading Materials	2.5	\$53.55	\$74.38	\$17.30	\$0.00	\$0.00	\$145.23
ODBH / Outfall ditch - bushhogged	14.0	\$303.60	\$471.82	\$81.31	\$0.00	\$0.00	\$856.73
OFPI / Outfall Pipe - Installation	54.0	\$1,251.73	\$482.47	\$1,305.99	\$0.00	\$0.00	\$3,040.19
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$2,818.04	\$2,818.04
2012-515 /Mint Farm Pond and Outfall Sub Total	185.5	\$4,129.93	\$2,041.24	\$3,994.75	\$0.00	\$2,818.04	\$12,983.95
Grand Total	185.5	\$4,129.93	\$2,041.24	\$3,994.75	\$0.00	\$2,818.04	\$12,983.95

Before



During



After



Project: Mint Farm Pond and Outfall

Activity: Drainage Maintenance















Project #: 2012-515

Township: Port Royal Island

Completed: August 2011

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels
-  Flapgate



1 inch = 230 feet