



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Dulamo Subdivision - Cusabo Road and Escamaco Circle

Narrative Description of Project:

Project improved 3,283 L.F. of drainage system. Cleaned out 3,283 L.F. of roadside ditch. Cleaned out (1) catch basin. Jetted (1) access pipe, (2) crossline pipes and (24) driveway pipes.

Completion: Feb-12

2012-508 / Dulamo Subdivision	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.5	\$30.72	\$0.00	\$0.00	\$0.00	\$0.00	\$30.72
DPJT / Driveway Pipe - Jetted	50.0	\$1,103.25	\$460.00	\$238.21	\$0.00	\$0.00	\$1,801.46
HAUL / Hauling	77.0	\$1,659.64	\$991.60	\$359.52	\$0.00	\$0.00	\$3,010.75
HYDR / Hydroseeding	14.0	\$301.98	\$74.18	\$187.55	\$0.00	\$0.00	\$765.91
PRRECON / Project Reconnaissance	4.0	\$93.12	\$16.28	\$13.44	\$0.00	\$0.00	\$122.84
RS / Road Sweep	10.0	\$204.80	\$101.00	\$51.74	\$0.00	\$0.00	\$489.84
RSDCL / Roadside Ditch - Cleanout	267.0	\$6,016.97	\$1,187.13	\$394.25	\$0.00	\$0.00	\$7,598.35
UTLOC / Utility locates	1.5	\$30.72	\$0.00	\$0.00	\$0.00	\$0.00	\$30.72
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$6,484.23	\$6,484.23
2012-508 / Dulamo Subdivision Sub Total	425.0	\$9,441.20	\$2,830.19	\$1,244.71	\$0.00	\$6,484.23	\$20,334.82
 Grand Total	 425.0	 \$9,441.20	 \$2,830.19	 \$1,244.71	 \$0.00	 \$6,484.23	 \$20,334.82

Before



During



After



Project: Dulamo Subdivision - Escamaco Circle and Cusabo Road

Activity: Drainage Maintenance














Project #: 2012-508

Township: St. Helena Island

Completed: February 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels

Jetted (24) driveway pipes.

Jetted (1) crossline pipe. Cleaned out (1) catch basin.

Cleaned out 520 LF of roadside ditch.

Cleaned out 360 LF of roadside ditch.

Cleaned out 320 LF of roadside ditch.

Jetted (1) crossline pipe.

Cleaned out 230 LF of roadside ditch.

Cleaned out 1,060 LF of roadside ditch.

Jetted (1) access pipe.

Cleaned out 793 LF of roadside ditch.



1 inch = 259 feet