



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Daufuskie Island - Benjies Point Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Replaced (1) crossline pipe.

Completion: Apr-13

2013-692 / Daufuskie Island - Benjies Point Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
CPRPL / Crossline Pipe - Replaced	50.0	\$1,135.30	\$40.20	\$455.20	\$0.00	\$543.20	\$2,173.90
ONJV / Onsite Job Visit	10.0	\$246.10	\$40.20	\$19.84	\$0.00	\$182.30	\$488.44
2013-692 / Daufuskie Island - Benjies Point Road Sub Total	60.5	\$1,391.85	\$80.40	\$475.04	\$0.00	\$732.12	\$2,679.40
Grand Total	60.5	\$1,391.85	\$80.40	\$475.04	\$0.00	\$732.12	\$2,679.40

(Pictures Not Available)


Project: Benjies Point Road

Activity: Routine/ Preventive Maintenance

Project #: 2013-692
















Township: Daufuskie Island

Completed: April 2013



Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels



1 inch = 253 feet