



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Daufuski Island- Haig Point Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Aug-13

Installed (1) driveway pipe.

2014-525 / Daufuski Island- Haig Point Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
DPINS / Driveway Pipe - Installed	40.0	\$1,006.67	\$123.79	\$215.10	\$0.00	\$696.50	\$2,042.05
UTLOC / Utility locates	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
2014-525 / Daufuski Island- Haig Point Road Sub Total	41.0	\$1,027.13	\$123.79	\$215.10	\$0.00	\$709.73	\$2,075.75
Grand Total	41.0	\$1,027.13	\$123.79	\$215.10	\$0.00	\$709.73	\$2,075.75

Before



During



After



Project: Daufuskie Island-Haig Point Road

Activity: Routine/ Preventative Maintenance

Project #: 2014-525

Township: Daufuskie Island

Completed: August 2013

Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- ▬ Channel Pipe
- Lateral
- ▬ Lateral Pipe
- Roadside
- ▬ Roadside Pipe
- ▬ Road Pipe
- ▬ Crossline Pipe
- ▬ Driveway Pipe
- ▬ Access Pipe
- Bleeder Pipe
- Catch Basin

Installed (1) driveway pipe.



1 inch = 133 feet