



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Sheldon Washout Repair - Backache Acres

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired washout.

Completion: Aug-13

2014-516 / Sheldon Washout Repair	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
RPWO / Repaired Washout	10.0	\$216.64	\$59.77	\$35.55	\$0.00	\$110.78	\$422.74
2014-516 / Sheldon Washout Repair	10.5	\$226.87	\$59.77	\$35.55	\$0.00	\$117.40	\$439.59
Sub Total							
Grand Total	10.5	\$226.87	\$59.77	\$35.55	\$0.00	\$117.40	\$439.59

Before



After



Project: Backache Acres

Activity: Routine/ Preventive Maintenance

Project #: 2014-516

Township: Sheldon

Completed: August 2013



Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe



1 inch = 205 feet