



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Blacksmith Circle

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Repaired (2) washouts.

**Completion:** Jan-13

<b>2013-593 / Blacksmith Circle</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	5.0	\$109.25	\$53.50	\$24.64	\$0.00	\$72.10	\$259.49
RPWO / Repaired Washout	25.0	\$533.50	\$36.49	\$22.02	\$0.00	\$225.90	\$817.91
<b>2013-593 / Blacksmith Circle</b>	<b>30.5</b>	<b>\$653.20</b>	<b>\$89.99</b>	<b>\$46.66</b>	<b>\$0.00</b>	<b>\$304.61</b>	<b>\$1,094.46</b>
<b>Sub Total</b>							
<b>Grand Total</b>	<b>30.5</b>	<b>\$653.20</b>	<b>\$89.99</b>	<b>\$46.66</b>	<b>\$0.00</b>	<b>\$304.61</b>	<b>\$1,094.46</b>

**Before**



**During**



**After**



**Project: Blacksmith Circle**

**Activity: Routine/  
Preventive  
Maintenance**















**Project #:  
2013-593**

**Township: Port  
Royal Island**

**Completed:  
January 2013**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



**1 inch = 61 feet**