



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Buck Point Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Cleaned out (1) catch basin. Jetted (1) crossline pipe.

Completion: Jul-13

2013-656 / Buck Point Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CLPJT / Crossline Pipe - Jetted	6.0	\$129.76	\$66.48	\$73.30	\$0.00	\$49.41	\$318.95
2013-656 / Buck Point Road Sub Total	6.5	\$139.99	\$66.48	\$73.30	\$0.00	\$56.03	\$335.80
Grand Total	6.5	\$139.99	\$66.48	\$73.30	\$0.00	\$56.03	\$335.80

Before



During



After



Project: Buck Point Road

Activity: Routine/ Preventive Maintenance
















Project #: 2014-656

Township: Bluffton

Completed: July 2013

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Catch Basin



1 inch = 170 feet