



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Lost Island Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired washout.

Completion: Jul-13

2014-508 / Lost Island Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	9.0	\$194.65	\$96.30	\$53.38	\$0.00	\$129.78	\$474.11
ONJV / Onsite Job Visit	2.0	\$59.68	\$7.24	\$4.74	\$0.00	\$36.46	\$108.12
RPWO / Repaired Washout	14.0	\$317.91	\$100.39	\$54.29	\$0.00	\$213.66	\$686.24
2014-508 / Lost Island Road Sub Total	25.5	\$582.47	\$203.93	\$112.40	\$0.00	\$386.52	\$1,285.32
Grand Total	25.5	\$582.47	\$203.93	\$112.40	\$0.00	\$386.52	\$1,285.32

Before



During



After





Project: Lost Island Road

Activity: Routine/ Preventive Maintenance

Project #: 2013-508

Township: Lady's Island

Completed: July 2013



Legend	
TYPE	
	River
	Creek/Stream
	River/Creek/Marsh BANK
	Channel (fka Outfall)
	Channel Pipe
	Lateral
	Lateral Pipe
	Roadside
	Roadside Pipe
	Road Pipe
	Crossline Pipe
	Driveway Pipe
	Access Pipe
	Bleeder Pipe
	Catch Basin



1 inch = 76 feet