



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Lost Island Road

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 1,932 L.F. of drainage system. Cleaned out 1,932 L.F. of roadside ditch. Jetted (1) crossline pipe and (9) driveway pipes. Hydroseeded for erosion control.


**Completion:** Mar-13

2013-618 / Lost Island Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
CLPJT / Crossline Pipe - Jetted	24.0	\$566.76	\$265.92	\$59.31	\$0.00	\$389.64	\$1,281.63
DPJT / Driveway Pipe - Jetted	8.0	\$188.92	\$88.64	\$48.70	\$0.00	\$129.88	\$456.14
HAUL / Hauling	26.0	\$571.52	\$246.10	\$117.95	\$0.00	\$356.03	\$1,291.60
ONJV / Onsite Job Visit	11.0	\$343.42	\$44.22	\$37.20	\$0.00	\$269.17	\$694.01
RSDCL / Roadside Ditch - Cleanout	60.0	\$1,318.40	\$240.35	\$212.63	\$0.00	\$867.00	\$2,638.38
<b>2013-618 / Lost Island Road</b>	<b>129.5</b>	<b>\$2,999.47</b>	<b>\$885.23</b>	<b>\$475.79</b>	<b>\$0.00</b>	<b>\$2,018.34</b>	<b>\$6,378.82</b>
<b>Grand Total</b>	<b>129.5</b>	<b>\$2,999.47</b>	<b>\$885.23</b>	<b>\$475.79</b>	<b>\$0.00</b>	<b>\$2,018.34</b>	<b>\$6,378.82</b>

Before



During



After



**Project: Lost Island Road**

**Activity: Routine/ Preventive Maintenance**
















**Project #: 2013-618**

**Township: Lady's Island**

**Completed: April 2013**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels

Cleaned out 1,275 LF of roadside ditch. Hydroseeded for erosion control.

Cleaned out 657 LF of roadside ditch. Hydroseeded for erosion control.

Jetted (9) driveway pipes.

Jetted (1) crossline pipe.



1 inch = 236 feet