



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Ardmore Avenue

**Activity:** Routine/Preventive Maintenance

## Narrative Description of Project:

**Completion:** May-13

Project improved 134 L.F. of drainage system. Repaired (1) catch basin. Replaced 10 L.F. channel pipe. Cleaned out (1) catch basin. Jetted (1) and 124 L.F. of channel pipe. Handseeded for erosion control.

| 2013-682 / Ardmore Avenue        | Labor<br>Hours | Labor<br>Cost     | Equipment<br>Cost | Material<br>Cost | Contractor<br>Cost | Indirect<br>Labor | Total Cost        |
|----------------------------------|----------------|-------------------|-------------------|------------------|--------------------|-------------------|-------------------|
| AUDIT / Audit Project            | 0.5            | \$10.45           | \$0.00            | \$0.00           | \$0.00             | \$6.62            | \$17.06           |
| CLJS / Cleaned up jobsite        | 9.0            | \$202.86          | \$12.06           | \$48.85          | \$0.00             | \$135.54          | \$399.31          |
| HAUL / Hauling                   | 10.0           | \$218.50          | \$107.00          | \$51.05          | \$0.00             | \$144.20          | \$520.75          |
| OFPJ / Outfall Pipe - Jetted     | 20.0           | \$472.30          | \$221.60          | \$80.55          | \$0.00             | \$324.70          | \$1,099.15        |
| OFPRP / Outfall Pipe - Replaced  | 30.0           | \$676.20          | \$62.29           | \$309.98         | \$0.00             | \$451.80          | \$1,500.27        |
| ONJV / Onsite Job Visit          | 10.0           | \$312.20          | \$40.20           | \$21.70          | \$0.00             | \$244.70          | \$618.80          |
| PL / Project Layout              | 9.0            | \$202.86          | \$12.06           | \$10.11          | \$0.00             | \$135.54          | \$360.57          |
| PRRECON / Project Reconnaissance | 5.0            | \$157.64          | \$16.08           | \$12.40          | \$0.00             | \$123.84          | \$309.96          |
| UTLOC / Utility locates          | 2.0            | \$41.78           | \$0.00            | \$0.00           | \$0.00             | \$26.46           | \$68.24           |
| <b>2013-682 / Ardmore Avenue</b> | <b>95.5</b>    | <b>\$2,294.79</b> | <b>\$471.29</b>   | <b>\$534.63</b>  | <b>\$0.00</b>      | <b>\$1,593.40</b> | <b>\$4,894.10</b> |
| <b>Sub Total</b>                 |                |                   |                   |                  |                    |                   |                   |
| <b>Grand Total</b>               | <b>95.5</b>    | <b>\$2,294.79</b> | <b>\$471.29</b>   | <b>\$534.63</b>  | <b>\$0.00</b>      | <b>\$1,593.40</b> | <b>\$4,894.10</b> |

Before



During



After





**Project: Ardmore Avenue**

**Activity: Routine/  
Preventive  
Maintenance**















**Project #:  
2013-682**

**Township: Lady's  
Island**

**Completed:  
May 2013**

### Legend

#### TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe

Repaired (1) catch basin.  
Replaced 10 LF of channel pipe. Handseeded for erosion control.

Cleaned out (1) catch basin.  
Jetted (1) catch basin and  
124 LF of channel pipe.

**ARDMORE AVE**

**OGDEN CT**



0 15 30 60 90 120  
Feet

1 inch = 74 feet

Prepared By: BC Stormwater Management Utility  
Date Print: 5/29/13

File: C:\path\data\projects\project\Ardmore Ave 2013 000