



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Sheldon Washout Repairs - Mitchell Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired washouts.

Completion: May-13

2013-544A / Sheldon Washout Repair	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	6.0	\$142.50	\$24.12	\$46.49	\$0.00	\$98.82	\$311.92
WSREP / Workshelf - Repair	5.0	\$104.45	\$42.19	\$35.39	\$0.00	\$66.15	\$248.17
2013-544A / Sheldon Washout Repair Sub Total	11.5	\$257.40	\$66.31	\$81.87	\$0.00	\$171.58	\$577.16
Grand Total	11.5	\$257.40	\$66.31	\$81.87	\$0.00	\$171.58	\$577.16

(Pictures Not Available)

Project: Mitchell Road-Washout Repair

Activity: Routine/ Preventive Maintenance















Project #: 2013-544A

Township: Sheldon

Completed: May 2013

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe

Repaired washouts.



1 inch = 170 feet