



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Mulrain Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: May-14

Project improved 525 L.F. of drainage system. Cleaned out (1) catch basin and 525 L.F. of channel. Repaired (1) catch basin.

2014-625 / Mulrain Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CBCO / Catch basin - clean out	6.0	\$129.77	\$66.48	\$34.54	\$0.00	\$86.04	\$316.83
CBREP / Catch basin - repaired	28.0	\$625.56	\$43.44	\$163.13	\$0.00	\$398.04	\$1,230.17
HAUL / Hauling	13.0	\$302.07	\$139.10	\$170.49	\$0.00	\$203.33	\$814.99
ODCO / Outfall ditch - cleaned out	48.0	\$1,115.10	\$300.95	\$81.81	\$0.00	\$723.18	\$2,221.04
ONJV / Onsite Job Visit	7.0	\$212.22	\$25.34	\$21.00	\$0.00	\$133.85	\$392.41
2014-625 / Mulrain Road	102.5	\$2,394.95	\$575.31	\$470.97	\$0.00	\$1,551.06	\$4,992.29
Sub Total							
Grand Total	102.5	\$2,394.95	\$575.31	\$470.97	\$0.00	\$1,551.06	\$4,992.29


Before



During



After



Project: Mulrain Road

**Activity: Routine/
Preventive
Maintenance**















**Project #:
2014-625**

**Township: Port
Royal Island**

**Completed:
May 2014**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 141 feet