



# Beaufort County Public Works

## Stormwater Infrastructure

### Project Summary

**Project Summary:** Peaches Hill Circle

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

**Completion:** Mar-14

Project improved 865 L.F.of drainage system. Cleaned out 865 L.F. of roadside ditch.

2014-592 / Peaches Hill Circle	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	6.0	\$143.88	\$64.20	\$68.80	\$0.00	\$98.82	\$375.70
HYDR / Hydroseeding	4.0	\$84.18	\$14.59	\$79.22	\$0.00	\$55.30	\$233.29
ODCO / Outfall ditch - cleaned out	42.0	\$901.43	\$411.06	\$129.76	\$0.00	\$555.74	\$1,997.99
<b>2014-592 / Peaches Hill Circle</b>	<b>52.5</b>	<b>\$1,139.72</b>	<b>\$489.85</b>	<b>\$277.78</b>	<b>\$0.00</b>	<b>\$716.47</b>	<b>\$2,623.82</b>
<b>Sub Total</b>							
<b>Grand Total</b>	<b>52.5</b>	<b>\$1,139.72</b>	<b>\$489.85</b>	<b>\$277.78</b>	<b>\$0.00</b>	<b>\$716.47</b>	<b>\$2,623.82</b>

Before



During



After




**Project: Peaches Hill Circle**

**Activity: Routine/  
Preventive  
Maintenance**

**Project #:  
2014-592**

**Township: St.  
Helena Island**

**Completed:  
April 2014**



Cleaned out 865 LF of roadside ditch.

**Legend**

**TYPE**

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe



1 inch = 358 feet

Prepared By: BC Stormwater Management Utility

Date Print: 5/6/14

File:C:/sethdata/projects/projectmaps/Peaches Hill Cir 2014-592