



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Ardmore Avenue

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired sinkhole.

Completion: May-14

2014-620 / Ardmore Avenue	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CBREP / Catch basin - repaired	20.0	\$428.00	\$18.10	\$31.39	\$0.00	\$220.80	\$698.28
2014-620 / Ardmore Avenue	20.5	\$438.23	\$18.10	\$31.39	\$0.00	\$227.41	\$715.13
Sub Total							
Grand Total	20.5	\$438.23	\$18.10	\$31.39	\$0.00	\$227.41	\$715.13

Before



After

