



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Old Dawson Acres

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Repaired catch basin and sinkhole.

**Completion:** Nov-13

<b>2014-550 / Old Dawson Acres</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CBREP / Catch basin - repaired	11.0	\$256.75	\$0.00	\$30.24	\$0.00	\$109.71	\$396.70
HAUL / Hauling	3.0	\$64.89	\$32.10	\$23.31	\$0.00	\$43.26	\$163.56
ONJV / Onsite Job Visit	3.0	\$89.52	\$10.86	\$8.76	\$0.00	\$54.69	\$163.83
<b>2014-550 / Old Dawson Acres</b>	<b>17.5</b>	<b>\$421.39</b>	<b>\$42.96</b>	<b>\$62.31</b>	<b>\$0.00</b>	<b>\$214.28</b>	<b>\$740.93</b>
<b>Sub Total</b>							
<b>Grand Total</b>	<b>17.5</b>	<b>\$421.39</b>	<b>\$42.96</b>	<b>\$62.31</b>	<b>\$0.00</b>	<b>\$214.28</b>	<b>\$740.93</b>

(Pictures Not Available)


**Project: Old Dawson Acres**

**Activity: Routine/  
Preventive  
Maintenance**

**Project #:  
2014-550**

**Township:  
Sheldon**

**Completed:  
November 2013**



**Legend**

**TYPE**

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe
- Catch Basin



**1 inch = 117 feet**

Prepared By: BC Stormwater Management Utility

Date Print: 2/27/14

File:C:/sethdata/projects/projectmaps/Old Dawson Acres 2014-550