



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Buckwalter Parkway

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Repaired (2) catch basins and sinkholes.

**Completion:** Dec-13

2014-558 / Buckwalter Parkway	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CBREP / Catch basin - repaired	36.0	\$810.51	\$43.44	\$51.42	\$0.00	\$551.41	\$1,456.78
ONJV / Onsite Job Visit	5.0	\$165.90	\$18.10	\$22.96	\$0.00	\$122.35	\$329.31
<b>2014-558 / Buckwalter Parkway Sub Total</b>	<b>41.5</b>	<b>\$986.64</b>	<b>\$61.54</b>	<b>\$74.38</b>	<b>\$0.00</b>	<b>\$680.37</b>	<b>\$1,802.94</b>
<b>Grand Total</b>	<b>41.5</b>	<b>\$986.64</b>	<b>\$61.54</b>	<b>\$74.38</b>	<b>\$0.00</b>	<b>\$680.37</b>	<b>\$1,802.94</b>

Before



During



After



Project: Buckwalter Parkway

Activity: Routine/  
Preventive  
Maintenance
















Project #:  
2014-558

Township:  
Bluffton

Completed:  
December 2013

### Legend

#### TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Catch Basin



Repaired (2)  
catch basins.



1 inch = 35 feet