



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Greenleaf Lane

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired washout. Installed rip rap and handseeded for erosion control.

Completion: Dec-13

2014-559 / Greenleaf Lane	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	3.0	\$57.84	\$32.10	\$401.10	\$0.00	\$40.20	\$531.24
ONJV / Onsite Job Visit	2.0	\$66.36	\$7.24	\$8.61	\$0.00	\$48.94	\$131.15
RPWO / Repaired Washout	6.0	\$134.10	\$10.86	\$84.04	\$0.00	\$89.73	\$318.73
2014-559 / Greenleaf Lane Sub Total	11.5	\$268.53	\$50.20	\$493.75	\$0.00	\$185.49	\$997.97
Grand Total	11.5	\$268.53	\$50.20	\$493.75	\$0.00	\$185.49	\$997.97

Before



During



After



Project: Greenleaf Lane

**Activity: Routine/
Preventive
Maintenance**















**Project #:
2014-559**

**Township: Port
Royal Island**

**Completed:
December 2013**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe

Repaired washout.
Installed rip rap and
handseeded for erosion
control

GREENLEAF LN



1 inch = 54 feet

Prepared By: BC Stormwater Management Utility

Date Print: 2/12/14

File:C:/sethdata/projects/projectmaps/Greenleaf Ln 2014-559