

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Parkside Drive

Narrative Description of Project:

Repaired (1) catch basin lid and washout.

Activity: Routine/Preventive Maintenance

Completion: Jul-14

2015-501 / Parkside Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project CBLREP / Catch Basin Lid - Repaired ONJV / Onsite Job Visit RPWO / Repaired Washout 2015-501 / Parkside Drive Sub Total	0.5 22.0 8.0 12.0 42.5	\$10.23 \$496.71 \$238.72 \$274.72 \$1,020.38	\$0.00 \$19.91 \$28.96 \$14.48 \$63.35	\$0.00 \$26.05 \$16.00 \$28.80 \$70.85	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$6.62 \$312.13 \$145.84 \$169.32 \$633.90	\$16.85 \$854.79 \$429.52 \$487.32 \$1,788.48
Grand Total	42.5	\$1,020.38	\$63.35	\$70.85	\$0.00	\$633.90	\$1,788.48


Before











0 20 40 80 120 160 Feet

1 inch = 77 feet

Prepared By: BC Stormwater Management Utility Date Print: 9/8/14 File:C:/sethdata/projects/projectmaps/Parkside Dr 2015-501