



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Pin Oak Street/Able Street

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired curb inlet and sinkholes.

Completion: Jul-14

2015-510 / Pin Oak Street/Able Street	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	19.0	\$410.97	\$203.30	\$166.96	\$0.00	\$260.72	\$1,041.95
ONJV / Onsite Job Visit	14.0	\$432.19	\$50.68	\$48.00	\$0.00	\$270.95	\$801.82
RCI / Repaired Curb Inlet	42.0	\$945.98	\$63.69	\$132.73	\$0.00	\$598.45	\$1,740.85
UTLOC / Utility locates	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
2015-510 / Pin Oak Street/Able Street Sub Total	76.0	\$1,809.60	\$317.67	\$347.69	\$0.00	\$1,143.35	\$3,618.30
Grand Total	76.0	\$1,809.60	\$317.67	\$347.69	\$0.00	\$1,143.35	\$3,618.30

Before



During



After



Project: Pin Oak Street and Able Street

Activity: Routine/ Preventive Maintenance















Project #: 2015-510

Township: Bluffton

Completed: July 2014

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe

Repaired curb inlet and sinkhole.

Repaired sinkhole.



1 inch = 142 feet

Prepared By: BC Stormwater Management Utility

Date Print: 9/18/14

File:C:/sethdata/projects/projectmaps/Pin Oak St 2015-510