



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Ardmore Avenue - Rework

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Cleaned out (1) catch basin. Repaired catch basin and sinkhole.

Completion: Jun-14

2014-620R / Ardmore Avenue - Rework	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CBCO / Catch basin - clean out	13.0	\$292.92	\$199.44	\$52.82	\$0.00	\$197.07	\$742.25
CBREP / Catch basin - repaired	34.0	\$790.54	\$136.28	\$174.39	\$0.00	\$522.12	\$1,623.33
ONJV / Onsite Job Visit	6.0	\$185.72	\$21.72	\$12.80	\$0.00	\$121.86	\$342.10
TRAIN / Training	1.0	\$19.28	\$0.00	\$0.00	\$0.00	\$12.21	\$31.49
2014-620R / Ardmore Avenue - Rework Sub Total	54.5	\$1,298.69	\$357.44	\$240.01	\$0.00	\$859.88	\$2,756.01
Grand Total	54.5	\$1,298.69	\$357.44	\$240.01	\$0.00	\$859.88	\$2,756.01

Before



During



After



Project: Ardmore Avenue

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2014-620R**

**Township: Lady's
Island**

**Completed:
June 2014**



Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe

0 45 90 180 270 360
Feet

1 inch = 175 feet

Prepared By: BC Stormwater Management Utility

Date Print: 9/18/14

File: C:/sethdata/projects/projectmaps/Ardmore 2014-620R