



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Holly Hall Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired washout. Installed rip rap for erosion control.

Completion: Aug-14

2015-521 / Holly Hall Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	5.0	\$102.30	\$0.00	\$0.00	\$0.00	\$66.15	\$168.45
HAUL / Hauling	4.0	\$86.52	\$42.80	\$434.97	\$0.00	\$57.68	\$621.97
ONJV / Onsite Job Visit	2.0	\$66.36	\$7.24	\$9.09	\$0.00	\$48.94	\$131.63
RPWO / Repaired Washout	24.0	\$502.70	\$58.20	\$44.44	\$0.00	\$328.09	\$933.43
2015-521 / Holly Hall Road Sub Total	35.0	\$757.88	\$108.24	\$488.49	\$0.00	\$500.86	\$1,855.47
Grand Total	35.0	\$757.88	\$108.24	\$488.49	\$0.00	\$500.86	\$1,855.47

During



After



Project: Holly Hall Road

**Activity: Routine/
Preventive
Maintenance**















**Project #:
2015-521**


**Township: Lady's
Island**

**Completed:
August 2014**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



0 70 140 280 420 560
Feet

1 inch = 279 feet

Prepared By: BC Stormwater Management Utility

Date Print: 9/10/14

File: C:/sethdata/projects/projectmaps/Holly Hall Rd 2015-521