



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Eastern Road Channel - Rework

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Repaired washout.

**Completion:** Apr-15

<b>2015-011R / Eastern Road Channel - Rework</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$11.40	\$0.00	\$0.00	\$0.00	\$6.62	\$18.01
HAUL / Hauling	6.0	\$129.78	\$47.94	\$819.61	\$0.00	\$86.52	\$1,083.85
ONJV / Onsite Job Visit	2.0	\$59.68	\$7.08	\$1.93	\$0.00	\$36.46	\$105.15
RPWO / Repaired Washout	12.0	\$331.77	\$48.73	\$16.14	\$0.00	\$234.36	\$631.00
<b>2015-011R / Eastern Road Channel - Rework Sub Total</b>	<b>20.5</b>	<b>\$532.63</b>	<b>\$103.75</b>	<b>\$837.68</b>	<b>\$0.00</b>	<b>\$363.96</b>	<b>\$1,838.01</b>
<b>Grand Total</b>	<b>20.5</b>	<b>\$532.63</b>	<b>\$103.75</b>	<b>\$837.68</b>	<b>\$0.00</b>	<b>\$363.96</b>	<b>\$1,838.01</b>

Before



During



After



**Project: Eastern Road Channel - Rework**

**Activity: Routine/ Preventive Maintenance**















**Project #: 2015-011R**

**Township: Port Royal Island**

**Completed: April 2015**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



0 30 60 120 180 240 Feet

1 inch = 131 feet

Prepared By: BC Stormwater Management Utility

Date Print: 8/18/15

File:C:/sethdata/projects/projectmaps/Eastern Rd 2015-011R