



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Horace Dawson Lane

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Removed blockage from flowline by hand.

Completion: Nov-15


2016-557 / Horace Dawson Lane	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
ONJV / Onsite Job Visit	1.0	\$34.18	\$3.54	\$5.16	\$0.00	\$24.47	\$67.35
RB / Remove blockage from flowline	4.0	\$87.90	\$3.54	\$5.16	\$0.00	\$56.16	\$152.76
2016-557 / Horace Dawson Lane Sub Total	5.5	\$133.83	\$7.08	\$10.32	\$0.00	\$87.25	\$238.47
Grand Total	5.5	\$133.83	\$7.08	\$10.32	\$0.00	\$87.25	\$238.47

Before



After





Project: Horace Dawson Lane

Activity: Routine/ Preventive Maintenance














Project #: 2016-557

Township: Sheldon

Completed: November 2015

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 45 90 180 270 360 Feet

1 inch = 190 feet

Prepared By: BC Stormwater Management Utility
 Date Print: 11/03/15
 File: C:\project summaries map\Horace Dawson Lane_216-557