



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Clydesdale Circle

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Jetted (1) driveway pipe.

Completion: Dec-14

2015-561 / Clydesdale Circle	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
DPJT / Driveway Pipe - Jetted	4.0	\$89.35	\$44.32	\$20.65	\$0.00	\$59.82	\$214.14
2015-561 / Clydesdale Circle Sub Total	4.5	\$99.58	\$44.32	\$20.65	\$0.00	\$66.44	\$230.99
Grand Total	4.5	\$99.58	\$44.32	\$20.65	\$0.00	\$66.44	\$230.99

Before



During



After



Project: Clydesdale Circle

Activity: Vacuum Truck

Project #: 2015-561















Township: Port Royal Island

Completed: December 2014



Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 229 feet