



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Pine Grove Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired washout. Hydroseeded for erosion control.

Completion: Sep-14

2015-541 / Pine Grove Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	2.0	\$43.26	\$21.40	\$22.93	\$0.00	\$28.84	\$116.43
ONJV / Onsite Job Visit	2.0	\$59.68	\$7.24	\$3.05	\$0.00	\$36.46	\$106.43
RPWO / Repaired Washout	11.0	\$243.18	\$45.30	\$96.04	\$0.00	\$153.06	\$537.58
2015-541 / Pine Grove Road Sub Total	15.5	\$356.35	\$73.94	\$122.02	\$0.00	\$224.98	\$777.29
Grand Total	15.5	\$356.35	\$73.94	\$122.02	\$0.00	\$224.98	\$777.29

(Pictures Not Available)


Project: Pine Grove Road

Activity: Routine/ Preventive Maintenance

Project #: 2015-541















Township: Port Royal Island

Completed: September 2014



Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 180 feet