



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Mary Elizabeth Drive

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Jetted (1) crossline pipe. Repaired sinkhole. Constructed swale for runoff. Installed sod for erosion control.

Completion: Sep-14

2015-535 / Mary Elizabeth Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CLPJT / Crossline Pipe - Jetted	16.0	\$375.06	\$177.28	\$94.12	\$0.00	\$255.12	\$901.58
HAUL / Hauling	15.0	\$324.45	\$160.50	\$64.00	\$0.00	\$216.30	\$765.25
ONJV / Onsite Job Visit	12.0	\$398.16	\$43.44	\$40.88	\$0.00	\$293.64	\$776.12
PI / Project Inspection	2.0	\$88.54	\$7.24	\$11.68	\$0.00	\$67.92	\$175.38
PRRECON / Project Reconnaissance	2.0	\$88.54	\$7.24	\$8.76	\$0.00	\$67.92	\$172.46
SCON / Swale - Constructed	39.8	\$872.82	\$44.52	\$21.02	\$0.00	\$581.17	\$1,519.53
SI / Sod - Installation	15.0	\$336.20	\$18.10	\$47.04	\$0.00	\$225.70	\$627.04
UTLOC / Utility locates	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
2015-535 / Mary Elizabeth Drive Sub Total	102.8	\$2,504.23	\$458.32	\$287.51	\$0.00	\$1,721.00	\$4,971.05
Grand Total	102.8	\$2,504.23	\$458.32	\$287.51	\$0.00	\$1,721.00	\$4,971.05

Before



After



Project: Mary Elizabeth Drive Map 1

Activity: Routine/ Preventive Maintenance















Project #: 2015-535

Township: Lady's Island

Completed: September 2014

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe

Repaired sinkhole. Constructed swale for runoff. Installed sod for erosion control.



1 inch = 151 feet

Prepared By: BC Stormwater Management Utility

Date Print: 12/29/14

File:C:/sethdata/projects/projectmaps/Mary Elizabeth Dr 2015-535 Map1

Project: Mary Elizabeth Drive Map 2

Activity: Vacuum Truck















Project #: 2015-535


Township: Lady's Island

Completed: September 2014

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 151 feet