



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: View Point Circle

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Replaced (1) driveway pipe.

Completion: May-15

2015-613 / View Point Circle	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.40	\$0.00	\$0.00	\$0.00	\$6.62	\$18.01
DPRPL / Driveway Pipe - Replaced	40.0	\$865.30	\$85.29	\$268.14	\$0.00	\$571.80	\$1,790.53
DWASPH / Driveway - Asphalt	24.0	\$543.72	\$28.32	\$27.24	\$0.00	\$353.28	\$952.56
HAUL / Hauling	14.0	\$302.82	\$111.86	\$830.88	\$0.00	\$201.88	\$1,447.44
ONJV / Onsite Job Visit	12.0	\$442.52	\$42.80	\$21.23	\$0.00	\$331.60	\$838.15
PI / Project Inspection	2.0	\$88.54	\$7.24	\$5.79	\$0.00	\$67.92	\$169.49
PL / Project Layout	1.0	\$44.27	\$3.62	\$3.86	\$0.00	\$33.96	\$85.71
PP / Project Preparation	26.0	\$564.79	\$24.78	\$13.51	\$0.00	\$373.80	\$976.88
UTLOC / Utility locates	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
2015-613 / View Point Circle Sub Total	120.0	\$2,873.59	\$303.91	\$1,170.65	\$0.00	\$1,947.47	\$6,295.61
 Grand Total	 120.0	 \$2,873.59	 \$303.91	 \$1,170.65	 \$0.00	 \$1,947.47	 \$6,295.61

Before



During



After





**Project: View
Point Circle**

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2015-613**

**Township: St.
Helena Island**

**Completed:
May 2015**

Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe

0 20 40 80 120 160
Feet

1 inch = 77 feet

Prepared By: BC Stormwater Management Utility

Date Print: 7/1/15

File:C:/sethdata/projects/projectmaps/View Point Cir 2015-613