



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Fairfield Road

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Reset (2) catch basin lids.

**Completion:** Jan-15

<b>2015-579 / Fairfield Road</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CBLRE / Catch Basin Lid - Reset	9.0	\$206.03	\$29.14	\$13.98	\$0.00	\$130.05	\$379.20
ONJV / Onsite Job Visit	1.0	\$33.18	\$3.62	\$6.54	\$0.00	\$24.47	\$67.81
<b>2015-579 / Fairfield Road Sub Total</b>	<b>10.5</b>	<b>\$249.44</b>	<b>\$32.76</b>	<b>\$20.52</b>	<b>\$0.00</b>	<b>\$161.14</b>	<b>\$463.85</b>
<b>Grand Total</b>	<b>10.5</b>	<b>\$249.44</b>	<b>\$32.76</b>	<b>\$20.52</b>	<b>\$0.00</b>	<b>\$161.14</b>	<b>\$463.85</b>

(Pictures Not Available)

**Project: Fairfield Road**

**Activity: Routine/  
Preventive  
Maintenance**















**Project #:  
2015-579**

**Township: Lady's  
Island**

**Completed:  
January 2015**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe

Reset (2) catch basin lids.



1 inch = 110 feet