



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Ladys Island Washout Repairs - Ogden Court and Ardmore Avenue

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

**Completion:** Aug-14

Repaired (2) washouts.

<b>2015-526 / Ladys Island Washout Repairs</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
ONJV / Onsite Job Visit	4.0	\$132.72	\$14.48	\$18.18	\$0.00	\$97.88	\$263.26
RPWO / Repaired Washout	15.0	\$330.35	\$71.60	\$50.61	\$0.00	\$205.45	\$658.01
<b>2015-526 / Ladys Island Washout Repairs Sub Total</b>	<b>19.5</b>	<b>\$473.30</b>	<b>\$86.08</b>	<b>\$68.79</b>	<b>\$0.00</b>	<b>\$309.94</b>	<b>\$938.11</b>
<b>Grand Total</b>	<b>19.5</b>	<b>\$473.30</b>	<b>\$86.08</b>	<b>\$68.79</b>	<b>\$0.00</b>	<b>\$309.94</b>	<b>\$938.11</b>

(Pictures Not Available)

**Project: Ardmore Avenue & Ogden Court**

**Activity: Routine/ Preventive Maintenance**

**Project #: 2015-526**

**Township: Lady's Island**

**Completed: August 2014**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 83 feet