



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Murray Drive

**Activity:** Routine/Preventive Maintenance

**Duration:** 11/2/17


**Narrative Description of Project:**

Project improved 140 L.F. of drainage system. Cleaned out 140 L.F. of channel.

<b>2018-527 / Murray Drive</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
CCO / Channel - cleaned out	20.0	\$423.25	\$75.26	\$8.92	\$0.00	\$195.45	\$702.88
HAUL / Hauling	5.0	\$111.35	\$47.10	\$22.30	\$0.00	\$72.10	\$252.85
UTLOC / Utility locates	0.5	\$12.35	\$0.00	\$0.00	\$0.00	\$6.62	\$18.97
2018-527 / Murray Drive Sub Total	26.0	\$557.85	\$122.36	\$31.22	\$0.00	\$274.17	\$985.59
<b>Grand Total</b>	<b>26.0</b>	<b>\$557.85</b>	<b>\$122.36</b>	<b>\$31.22</b>	<b>\$0.00</b>	<b>\$274.17</b>	<b>\$985.59</b>

(Pictures Not Available)





Project: Murray Drive

Activity: Routine/  
Preventive  
Maintenance

Project #:  
2018-527

Township/SW Dist:  
Port Royal Island/6

Completed:  
November 2017

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 100 feet

Prepared By: BC Stormwater Management Utility  
Date Print: 03/07/18  
File: C:\project summaries map\Murray Drive\_2018-527