



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** View Point Circle and Horse Island Drive

**Activity:** Routine/Preventive Maintenance

**Duration:** 03/01/18-03/08/18

**Narrative Description of Project:**

Project improved 340 L.F. of drainage system. Cleaned out 340 L.F. of roadside ditch.

2018-580 / View Point Circle	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
HAUL / Hauling	8.0	\$175.76	\$75.36	\$57.25	\$0.00	\$43.26	\$351.63
RSDCL / Roadside Ditch - Cleanout	40.0	\$818.40	\$110.31	\$25.19	\$0.00	\$386.70	\$1,340.60
UTLOC / Utility locates	1.0	\$24.70	\$0.00	\$0.00	\$0.00	\$13.23	\$37.93
2018-580 / View Point Circle Sub Total	49.5	\$1,029.76	\$185.67	\$82.44	\$0.00	\$443.19	\$1,741.06
<b>Grand Total</b>	<b>49.5</b>	<b>\$1,029.76</b>	<b>\$185.67</b>	<b>\$82.44</b>	<b>\$0.00</b>	<b>\$443.19</b>	<b>\$1,741.06</b>

**Before**



**During**



**After**







Project: Horse  
Island Drive and  
View Point Circle

Activity: Routine/  
Preventive  
Maintenance

Project #:  
2018-580

Township/SW Dist:  
St.Helena Island/8

Completed:  
March 2018

### Legend

#### Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 50 100 200 300 400  
Feet

1 inch = 210 feet

Prepared By: BC Stormwater Management Utility

Date Print:08/13/18

File:C:\project summaries map/Horse Island Drive & View Point Circle\_2018-580