



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Wallace Road

Activity: Routine/Preventive Maintenance

Duration: 08/10/17-02/26/18

Narrative Description of Project:

Dewatered channel. Jetted (1) crossline pipe.

2018-519 / Wallace Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
DC / Dewatered Channel	66.0	\$1,472.07	\$124.41	\$44.42	\$0.00	\$831.72	\$2,472.62
PP / Project Preparation	14.0	\$357.70	\$26.88	\$8.12	\$0.00	\$195.02	\$587.72
PRRECON / Project Reconnaissance	34.0	\$808.69	\$60.60	\$59.32	\$0.00	\$379.53	\$1,308.14
2018-519 / Wallace Road Sub Total	114.5	\$2,649.36	\$211.89	\$111.86	\$0.00	\$1,406.27	\$4,379.38
Grand Total	114.5	\$2,649.36	\$211.89	\$111.86	\$0.00	\$1,406.27	\$4,379.38

Before



During



After

(Picture Not Available)

Project: Wallace Road

Activity: Routine/
Preventive
Maintenance

Project #:
2018-519

Township/SW Dist:
Lady's Island/7

Completed:
February 2018



Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 180 feet