

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Sheldon Washout Repair Huspah Ct S, Jasmine Hall Road

Narrative Description of Project:

Installed (1) access pipe. Repaired washouts.

Activity: Routine/Preventive Maintenance Duration: 02/06/19-03/18/19

2019-318A / Sheldon Washout Repair	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
APINS / Access pipe - installed	90.0	\$1,921.20	\$402.02	\$674.29	\$0.00	\$858.60	\$3,856.11
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
HAUL / Hauling	49.0	\$1,151.98	\$693.84	\$3,054.31	\$0.00	\$757.83	\$5,657.96
PP / Project Preparation	12.0	\$265.86	\$10.80	\$16.31	\$0.00	\$128.79	\$421.76
RPWO / Repaired Washout	30.0	\$757.70	\$192.89	\$61.50	\$0.00	\$281.85	\$1,293.94
SG / Shoot Grade	15.0	\$334.13	\$60.94	\$17.48	\$0.00	\$214.65	\$627.19
STAGING / Staging Materials/Equipment	9.0	\$195.78	\$10.80	\$6.99	\$0.00	\$89.10	\$302.67
2019-318A / Sheldon Washout Repair Sub Total	206.0	\$4,648.44	\$1,371.29	\$3,830.87	\$0.00	\$2,330.82	\$12,181.42
Grand Total	206.0	\$4,648.44	\$1,371.29	\$3,830.87	\$0.00	\$2,330.82	\$12,181.42

Before



During

(Picture Not Available)

After





