



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Lady's Island Washout Repair  
Fiddler Drive, Varsity Lane, E River Drive

**Activity:** Routine/Preventive Maintenance

**Duration:** 07/09/19-10/24/19


**Narrative Description of Project:**

Repaired washouts. Installed rip rap and handseeded for erosion control.

**2020-516 / Lady's Island Washout**

	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
HAUL / Hauling	8.0	\$180.32	\$113.28	\$267.33	\$0.00	\$72.10	\$633.03
RPWO / Repaired Washout	39.0	\$953.48	\$132.84	\$96.92	\$0.00	\$370.95	\$1,554.19
2020-516 / Lady's Island Washout Sub Total	48.0	\$1,155.59	\$246.12	\$364.25	\$0.00	\$443.05	\$2,209.01
<b>Grand Total</b>	<b>48.0</b>	<b>\$1,155.59</b>	<b>\$246.12</b>	<b>\$364.25</b>	<b>\$0.00</b>	<b>\$443.05</b>	<b>\$2,209.01</b>

**Before**



**During**



**After**







Project: Lady's  
Island Washout  
Repair - Fiddler  
Drive  
Map #1

Activity: Routine/  
Preventive  
Maintenance

Project #:  
2020-516

Township/SW Dist:  
Lady's Island/7

Completed:  
October 2019

### Legend

#### Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 80 160 320 480 640  
Feet

1 inch = 350 feet

Prepared By: BC Stormwater Management Utility

Date Print: 01/15/20

File: C:\project summaries map\Lady's Island Washout Repair- Fiddler Drive Map #1\_2020-516





Project: Lady's  
Island Washout  
Repair - Varsity  
Street  
Map #2

Activity: Routine/  
Preventive  
Maintenance

Project #:  
2020-516

Township/SW Dist:  
Lady's Island/7

Completed:  
October 2019

#### Legend

##### Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 40 80 160 240 320  
Feet


1 inch = 170 feet

Prepared By: BC Stormwater Management Utility

Date Print: 01/15/20

File: C:\project summaries map\Lady's Island Washout Repair- Varsity Street Map #2\_2020-516





Project: Lady's  
Island Washout  
Repair - E River  
Drive  
Map #3

Activity: Routine/  
Preventive  
Maintenance

Project #:  
2020-516

Township/SW Dist:  
Lady's Island/7

Completed:  
October 2019

### Legend

#### Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 50 100 200 300 400  
Feet

1 inch = 210 feet

Prepared By: BC Stormwater Management Utility

Date Print: 01/15/20

File: C:\project summaries map\Lady's Island Washout Repair- E River Drive Map #3 2020-516