



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Sheldon Washout Repair  
Backache Acres

**Activity:** Routine/Preventive Maintenance

**Duration:** 08/27/19-08/28/19

**Narrative Description of Project:**

Replaced (1) bleeder pipe and installed rip rap for erosion control.

<b>2020-318 / Sheldon Washout Repair</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
BPREP / Bleeder Pipe - Replaced	30.0	\$652.55	\$161.40	\$357.41	\$0.00	\$297.00	\$1,468.36
HAUL / Hauling	3.0	\$66.81	\$42.48	\$304.61	\$0.00	\$43.26	\$457.16
RRI / Rip Rap - Installed	12.0	\$261.02	\$103.82	\$42.64	\$0.00	\$118.80	\$526.28
2020-318 / Sheldon Washout Repair Sub Total	46.0	\$1,002.17	\$307.70	\$704.65	\$0.00	\$459.06	\$2,473.58
<b>Grand Total</b>	<b>46.0</b>	<b>\$1,002.17</b>	<b>\$307.70</b>	<b>\$704.65</b>	<b>\$0.00</b>	<b>\$459.06</b>	<b>\$2,473.58</b>

**(No Pictures Available)**





Project: Sheldon  
Washout Repair-  
Backache Acres

Activity: Routine/  
Preventive  
Maintenance














Project #:  
2020-318

Township/SW Dist:  
Sheldon/5

Completed:  
August 2019

### Legend

#### Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 60 120 240 360 480  
Feet

1 inch = 250 feet

Prepared By: BC Stormwater Management Utility

Date Print: 01/22/20

File: C:\project summaries map\Sheldon Washout Repair-Backache Acres 2020-318