

## Beaufort County Public Works Stormwater Infrastructure

**Project Summary** 

**Project Summary:** Seigler Road Channel #2

**Activity:** Routine/Preventive Maintenance

**Duration:** 04/02/19-09/24/19

## **Narrative Description of Project:**

Installed (1) flap gate. Handseeded for erosion control.

2019-550A / Seigler Road Channel #2	Labor	Labor	<b>Equipment</b>	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
FLAPGATE / Flapgate - Installed	40.0	\$814.70	\$143.92	\$4,347.81	\$0.00	\$386.70	\$5,693.13
FLAPGATI / Flap Gate - Inspection	6.0	\$123.96	\$7.68	\$19.44	\$0.00	\$77.34	\$228.42
HAND / HANDSEEDED	6.0	\$123.96	\$7.68	\$41.50	\$0.00	\$77.34	\$250.48
HAUL / Hauling	31.0	\$704.77	\$438.96	\$682.94	\$0.00	\$158.62	\$1,985.29
LM / Loading Materials	15.0	\$309.90	\$19.20	\$17.28	\$0.00	\$193.35	\$539.73
STAGING / Staging Materials/Equipment	43.0	\$882.78	\$46.08	\$51.84	\$0.00	\$549.51	\$1,530.21
WSL / Workshelf - Level	30.0	\$607.80	\$99.60	\$570.00	\$0.00	\$376.50	\$1,653.90
2019-550A / Seigler Road Channel #2 Sub Total	172.0	\$3,589.66	\$763.12	\$5,730.81	\$0.00	\$1,819.36	\$11,902.95
Grand Total	172.0	\$3,589.66	\$763.12	\$5,730.81	\$0.00	\$1,819.36	\$11,902.95

Before During

(No Picture Available)

(No Picture Available)





