



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Irongate Subdivision - Blacksmith Circle

Activity: Routine/Preventive Maintenance


Narrative Description of Project:

Duration: 12/29/16 - 1/3/17

Repaired (1) catch basin.

2017-523 / Irongate Subdivision	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contracto Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
BKFILL / Back Fill	27.0	\$657.72	\$64.63	\$32.97	\$0.00	\$391.71	\$1,147.03
CBREP / Catch basin - repaired	18.0	\$432.54	\$21.60	\$85.88	\$0.00	\$258.84	\$798.86
HAUL / Hauling	2.0	\$44.54	\$18.84	\$28.43	\$0.00	\$28.84	\$120.65
SD / Soft Digging	30.0	\$686.40	\$130.20	\$64.60	\$0.00	\$445.50	\$1,326.70
2017-523 / Irongate Subdivision Sub Total	77.5	\$1,832.95	\$235.27	\$211.88	\$0.00	\$1,131.50	\$3,411.60
 Grand Total	 77.5	 \$1,832.95	 \$235.27	 \$211.88	 \$0.00	 \$1,131.50	 \$3,411.60

(Pictures Not Available)



Project: Blacksmith Circle

Activity: Routine/
Preventive
Maintenance

Project #:
2017-523

Township/SW Dist:
Port Royal Island/6

Completed:
January 2017

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 50 100 200 300 400
Feet

1 inch = 210 feet

Prepared By: BC Stormwater Management Utility

Date Print: 08/03/17

File: C:\project summaries map\Blacksmith Circle_2017-523