



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Irongate Subdivision - Blacksmith Circle

Activity: Routine/Preventive Maintenance


Narrative Description of Project:

Repaired catch basin.

Duration: 5/2/17 - 6/27/17

2017-547 / Irongate Subdivision	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
CBREP / Catch basin - repaired	40.0	\$903.00	\$129.26	\$235.65	\$0.00	\$541.10	\$1,809.01
HAUL / Hauling	10.0	\$222.70	\$94.20	\$18.94	\$0.00	\$144.20	\$480.04
UTLOC / Utility locates	1.0	\$24.70	\$0.00	\$0.00	\$0.00	\$13.23	\$37.93
2017-547 / Irongate Subdivision Sub Total	51.5	\$1,162.15	\$223.46	\$254.59	\$0.00	\$705.15	\$2,345.34
Grand Total	51.5	\$1,162.15	\$223.46	\$254.59	\$0.00	\$705.15	\$2,345.34

(Pictures Not Available)



Project: Irongate Subdivision-Blacksmith Circle

Activity: Routine/Preventive Maintenance

Project #: 2017-547

Township/SW Dist: Port Royal Island/6

Completed: June 2017

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 25 50 100 150 200 Feet

1 inch = 100 feet

Prepared By: BC Stormwater Management Utility

Date Print: 11/01/17

File: C:\project summaries map\Irongate S/D- Blacksmith Circle_2017-547