



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

Project Summary: Pine Run Trail  
 Project #: 2011-538                      Completed: Oct-10  
 Narrative Description of Project:  
 Removed blockage from flowline. Deleted crossline pipe to outfall ditch.

**Material Cost, Rental Equipment Summary, and Labor**

Material	Unit	Cost/Unit	Qty	Cost
Quikrete Concrete	bag	\$3.19	1.0	\$3.19
All Purpose Sand	bag	\$3.80	1.0	\$3.80
Gas	gallon	\$2.49	9.5	\$23.66
Labor	hours		11.5	\$265.26
Indirect Labor, Services, and Supplies				\$186.75
<b>Total Cost of Materials, Rental Equip., and Labor</b>				<b>\$482.66</b>

Note: Labor cost includes the employee's salary plus fringe benefits.

**Equipment Cost**

Item	Asset	Cost/Hour	Hrs.	Cost
Pickup Trucks		\$4.12	6.0	\$24.72
<b>Total Equipment Cost</b>				<b>\$24.72</b>

Cost/hour excludes fuel cost.

Total Cost:                      \$507.38

**Site Photographs**

Before



After



Project: Pine Run Trail

Activity: Drainage Maintenance














Project #: 2011-538

Township: Lady's Island

Completed: October 2010

### Legend

#### Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



Removed blockage from flowline.

Deleted crossline pipe to outfall ditch.



1 inch = 121 feet