



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: William Campbell Road Outfall

Narrative Description of Project:

Project improved 1,655 L.F. of drainage system. Cleaned out 1,655 L.F. of outfall ditch. Installed (1) access gate.

Completion: Oct-12

2013-565 / William Campbell Road Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AGI / Access Gate - Installed	8.0	\$182.94	\$16.08	\$184.76	\$0.00	\$116.26	\$500.04
AGP / Access Gate - Painted	2.0	\$41.74	\$4.02	\$7.12	\$0.00	\$26.46	\$79.34
AUDIT / Audit Project	1.0	\$20.89	\$0.00	\$0.00	\$0.00	\$13.23	\$34.12
DLO / Ditch Layout	20.0	\$449.30	\$40.20	\$24.47	\$0.00	\$266.70	\$780.67
HAUL / Hauling	20.0	\$437.00	\$214.00	\$96.12	\$0.00	\$288.40	\$1,035.52
ODCO / Outfall ditch - cleaned out	13.0	\$342.63	\$249.26	\$119.51	\$0.00	\$247.67	\$959.07
2013-565 / William Campbell Road Outfall	64.0	\$1,474.50	\$523.56	\$431.98	\$0.00	\$958.72	\$3,388.76
Grand Total	64.0	\$1,474.50	\$523.56	\$431.98	\$0.00	\$958.72	\$3,388.76

Before



During



After



Project: William Campbell Road Outfall

Activity: Drainage Maintenance














Project #: 2013-565


Township: Lady's Island

Completed: October 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 149 feet