



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Ladys Island Tree Removal - Francis Marion Circle

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Removed fallen tree from workshelf.

Completion: Aug-13

2014-517 / Ladys Island Tree Removal	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	3.0	\$64.89	\$32.10	\$67.92	\$0.00	\$43.26	\$208.17
RMTRW / Remove trees - Workshelf	9.0	\$202.47	\$27.49	\$13.16	\$0.00	\$135.54	\$378.66
2014-517 / Ladys Island Tree Removal Sub Total	12.5	\$277.59	\$59.59	\$81.08	\$0.00	\$185.42	\$603.67
Grand Total	12.5	\$277.59	\$59.59	\$81.08	\$0.00	\$185.42	\$603.67

Before



During



After



Project: Lady's Island Tree Removal
Francis Marion Circle















Activity: Routine/
Preventive
Maintenance

Project #:
2014-517

Township: Lady's
Island

Completed:
August 2013

Legend

- TYPE**
-  River
 -  Creek/Stream
 -  River/Creek/Marsh BANK
 -  Channel (fka Outfall)
 -  Channel Pipe
 -  Lateral
 -  Lateral Pipe
 -  Roadside
 -  Roadside Pipe
 -  Road Pipe
 -  Crossline Pipe
 -  Driveway Pipe
 -  Access Pipe
 -  Bleeder Pipe

Removed fallen tree
from workshelf.



1 inch = 125 feet