



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Judge Island Drive

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Sep-14

Upsized (1) crossline pipe.

2015-524 / Judge Island Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
BKFILL / Back Fill	10.0	\$204.60	\$80.20	\$29.20	\$0.00	\$132.30	\$446.30
CLJS / Cleaned up jobsite	16.0	\$356.55	\$36.48	\$23.64	\$0.00	\$226.32	\$642.99
CPUP / Crossline Pipe - Upsized	40.0	\$891.40	\$127.43	\$275.30	\$0.00	\$555.60	\$1,849.73
HAUL / Hauling	23.0	\$497.49	\$246.10	\$416.28	\$0.00	\$331.66	\$1,491.53
ONJV / Onsite Job Visit	18.0	\$543.80	\$65.16	\$40.88	\$0.00	\$340.62	\$990.46
STAGING / Staging Materials	20.0	\$450.23	\$18.10	\$35.04	\$0.00	\$302.10	\$805.47
UTLOC / Utility locates	2.5	\$76.59	\$7.24	\$8.76	\$0.00	\$55.56	\$148.15
2015-524 / Judge Island Drive Sub Total	130.0	\$3,030.89	\$580.71	\$829.10	\$0.00	\$1,950.77	\$6,391.47
 Grand Total	 130.0	 \$3,030.89	 \$580.71	 \$829.10	 \$0.00	 \$1,950.77	 \$6,391.47

Before



During



After



**Project: Judge
Island Drive**

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2015-524**















**Township: Lady's
Island**

**Completed:
September 2014**

Upsized (1)
crossline pipe.

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe

0 37.5 75 150 225 300
Feet

1 inch = 149 feet

Prepared By: BC Stormwater Management Utility

Date Print: 10/27/14

File: C:/sethdata/projects/projectmaps/Judge Is Dr 2015-524