



Beaufort County Public Works Stormwater Infrastructure *Project Summary*

Project Summary: Luther Lane Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Mar-14


Project improved 396 L.F. drainage system. Cleaned out 396 L.F. of channel. Hydroseeded for erosion control.

2014-594 / Candy Johnson Dr Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	17.0	\$364.77	\$181.90	\$99.76	\$0.00	\$245.14	\$891.57
HYDR / Hydroseeding	30.0	\$590.20	\$115.88	\$159.06	\$0.00	\$254.40	\$1,119.54
ODCO / Outfall ditch - cleaned out	72.0	\$1,543.10	\$203.65	\$110.89	\$0.00	\$978.05	\$2,835.69
2014-594 / Candy Johnson Dr Channel #1 Sub Total	119.5	\$2,508.30	\$501.43	\$369.71	\$0.00	\$1,484.20	\$4,863.64
Grand Total	119.5	\$2,508.30	\$501.43	\$369.71	\$0.00	\$1,484.20	\$4,863.64

Before



During



After



**Project: Luther Lane
Channel #1**

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2014-594**

**Township: St.
Helena Island**

**Completed:
March 2014**

Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- ▬ Channel Pipe
- Lateral
- ▬ Lateral Pipe
- Roadside
- ▬ Roadside Pipe
- ▬ Road Pipe
- ▬ Crossline Pipe
- ▬ Driveway Pipe
- ▬ Access Pipe
- ▬ Bleeder Pipe

Cleaned out 396 LF
of channel. Hydroseeded
for erosion control.



1 inch = 130 feet