



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Spanish Moss Subdivision - Oleander Drive

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

**Duration:** 6/27/16 - 8/24/16

Project improved 135 L.F. of drainage system. Cleaned out 135 L.F. of roadside ditch.  
Hydroseeded for erosion control.

<b>2016-630 / Spanish Moss Subdivision</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
HYDR / Hydroseeding	12.0	\$263.67	\$17.02	\$124.81	\$0.00	\$165.42	\$570.92
RSDCL / Roadside Ditch - Cleanout	16.0	\$352.80	\$91.39	\$43.46	\$0.00	\$213.72	\$701.37
SG / Shoot Grade	30.0	\$680.40	\$35.40	\$16.00	\$0.00	\$398.60	\$1,130.40
<b>2016-630 / Spanish Moss Subdivision Sub Total</b>	<b>58.5</b>	<b>\$1,308.61</b>	<b>\$143.81</b>	<b>\$184.27</b>	<b>\$0.00</b>	<b>\$784.36</b>	<b>\$2,421.05</b>
<b>Grand Total</b>	<b>58.5</b>	<b>\$1,308.61</b>	<b>\$143.81</b>	<b>\$184.27</b>	<b>\$0.00</b>	<b>\$784.36</b>	<b>\$2,421.05</b>

(Pictures Not Available)



Project: Spanish Moss Subdivision - Oleander Drive

Activity: Routine/ Preventive Maintenance

Project #: 2016-630

Township/SW Dist: Ladys Island/7

Completed: August 2016

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 150 feet