



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Riverbank Drive

Narrative Description of Project:

Pipe Inspection. Repaired outfall pipe and driveway.

Completion: Feb-11

2011-057 / Riverbank Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Cost	Total Cost
AUDIT / Audit Project	1.00	\$20.48	\$0.00	\$0.00	\$0.00	\$0.00	\$20.48
CBLI / Catch Basin Lid - Installed	4.00	\$85.68	\$48.44	\$257.34	\$0.00	\$0.00	\$391.46
HAUL / Hauling	31.50	\$710.16	\$419.27	\$594.53	\$0.00	\$0.00	\$1,723.95
LBB / Locate Blind Box	26.00	\$639.50	\$145.82	\$31.47	\$0.00	\$0.00	\$816.79
LM / Loading Materials	21.50	\$495.36	\$123.32	\$45.04	\$0.00	\$0.00	\$663.72
LPLGL / Locate Pipe Leak/Gas Line	42.00	\$1,028.74	\$123.10	\$23.32	\$0.00	\$0.00	\$1,175.16
NONPRO / Non-Professional Services	0.00	\$0.00	\$0.00	\$0.00	\$3,799.00	\$0.00	\$3,799.00
OFPR / Outfall Pipe - Repaired	129.00	\$3,045.37	\$697.66	\$258.41	\$0.00	\$0.00	\$4,001.44
PCAM / Pole Camera System	6.00	\$128.49	\$12.36	\$8.67	\$0.00	\$0.00	\$149.52
SD / Soft Digging	10.00	\$214.15	\$110.80	\$24.84	\$0.00	\$0.00	\$349.79
UTLOC / Utility locates	1.00	\$20.48	\$0.00	\$0.00	\$0.00	\$0.00	\$20.48
Indirect Labor, Services, and Supplies	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$4,514.71	\$4,514.71
2011-057 / Riverbank Drive Sub Total	272.00	\$6,388.41	\$1,680.76	\$1,243.62	\$3,799.00	\$4,514.71	\$17,626.50
Grand Total	272.00	\$6,388.41	\$1,680.76	\$5,042.62	\$3,799.00	\$4,514.71	\$17,626.50

Before



During



After





Project: Riverbank Drive

Activity: Drainage Maintenance

Project #: 2011-057

Township: Port Royal Island

Completed: February 2011

Legend

Drainage Type

- River
- Stream
- Outfall
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline
- D/W
- Access
- Piped
- Bleeder
- Parcels

Repaired outfall pipe and driveway.

RIVERBANK DR

HOGARTH ST



1 inch = 81 feet