



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Country Manor (Rework 2)

**Narrative Description of Project:**

Hydroseeded for erosion control.

**Completion:** Oct-12

<b>2011-015R2 / Country Manor (Rework 2)</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HYDR / Hydroseeding	2.0	\$41.78	\$20.48	\$103.19	\$0.00	\$26.46	\$191.91
<b>2011-015R2 / Country Manor (Rework 2)</b>	<b>2.5</b>	<b>\$52.23</b>	<b>\$20.48</b>	<b>\$103.19</b>	<b>\$0.00</b>	<b>\$33.08</b>	<b>\$208.97</b>
<b>Sub Total</b>							
<b>Grand Total</b>	<b>2.5</b>	<b>\$52.23</b>	<b>\$20.48</b>	<b>\$103.19</b>	<b>\$0.00</b>	<b>\$33.08</b>	<b>\$208.97</b>

After



Project: Country Manor (Rework) 2

Activity: Drainage Maintenance














Project #: 2011-015R2

Township: Port Royal Island

Completed: October 2012

### Legend

#### Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 83 feet

Prepared By: BC Stormwater Management Utility

Date Print: 11/16/12

File: C:/sethdata/projects/projectmaps/Country Manor (Rework) 2011-015R2