



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Huron Drive Outfall

Narrative Description of Project:

Project improved 1,086 L.F. of drainage system. Bush hogged 596 L.F. outfall ditch and workshelf. Cleaned out 490 L.F. of outfall ditch. Weedeat around catch basins. Repaired washouts.

Completion: Aug-12

2013-542 / Huron Drive Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	20.0	\$437.00	\$214.00	\$82.66	\$0.00	\$288.40	\$1,022.06
ODBH / Outfall ditch - bushhogged	10.0	\$208.90	\$59.83	\$32.96	\$0.00	\$132.30	\$433.99
ODCO / Outfall ditch - cleaned out	20.0	\$491.30	\$105.76	\$30.40	\$0.00	\$345.10	\$972.56
2013-542 / Huron Drive Outfall Sub Total	50.5	\$1,147.65	\$379.59	\$146.02	\$0.00	\$772.42	\$2,445.67
Grand Total	50.5	\$1,147.65	\$379.59	\$146.02	\$0.00	\$772.42	\$2,445.67

Before



During



After



Project: Huron Drive Outfall
Map 1

Activity: Drainage Maintenance














Project #: 2013-542


Township: Port Royal Island

Completed: August 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 133 feet



Project: Huron Drive Outfall
Map 2

Activity: Drainage Maintenance

Project #: 2013-542

Township: Port Royal Island

Completed: August 2012



Legend

Drainage Type

- River
- Stream
- Outfall
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Crossline
- D/W
- Access
- Piped
- Bleeder
- Parcels



1 inch = 167 feet