



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Port Royal Island Repaired Washouts - Colonial Avenue and Pine Grove Road

Activity: Preventive Maintenance


Narrative Description of Project:

Repaired washouts.

Completion: Oct-12

2013-552 / Port Royal Island - Repaired Washouts	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	6.0	\$131.10	\$64.20	\$30.22	\$0.00	\$86.52	\$312.04
RPWO / Repaired Washout	3.0	\$62.67	\$31.69	\$12.46	\$0.00	\$39.69	\$146.51
2013-552 / Port Royal Island - Repaired Washouts Sub Total	9.5	\$204.22	\$95.89	\$42.68	\$0.00	\$132.83	\$475.61
Grand Total	9.5	\$204.22	\$95.89	\$42.68	\$0.00	\$132.83	\$475.61

(Pictures Not Available)



Project: Colonial Avenue - PRI
 Repaired Washouts

Activity: Preventative Maintenance

Project #: 2013-522

Township: Port Royal Island

Completed: October 2012

Legend

Drainage Type

	River
	Stream
	Outfall
	Lateral
	Lateral Pipe
	Roadside
	Roadside Pipe
	Crossline
	D/W
	Access
	Piped
	Bleeder
	Parcels



1 inch = 165 feet

Prepared By: BC Stormwater Management Utility
 Date Print: 1/2/13
 File: C:/sethdata/projects/projectmaps/Colonial Ave 2013-522

Project: Pine Grove Road - PRI Repaired Washouts

Activity: Preventative Maintenance














Project #: 2013-522

Township: Port Royal Island

Completed: October 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



Repaired washout.



1 inch = 179 feet